

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403706380

Date Received:
03/15/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name
TEP

Phone

Email

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708902315

Inspection Date: 11/21/2023

FIR Submit Date: 11/23/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335272

Location Name: CLOUGH-66S94W Number: 20NESE County: _____

Qtrqr: NESE Sec: 20 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.509389 Longitude: -107.905230

FACILITY - API Number: 05-045- -00 Facility ID: 335272

Facility Name: CLOUGH-66S94W Number: 20NESE

Qtrqr: NESE Sec: 20 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.509389 Longitude: -107.905230

CORRECTIVE ACTIONS:

1 ☒ CA# 188494

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 12/08/2023

Response: CA COMPLETED

Date of Completion: 12/04/2023

Operator Comment: Location and access road has been bladed/graded to repair rills/tunnel erosion and to further stabilize road and pad surface. Corrective Action complete.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

Location and access road has been bladed/graded to repair rills/tunnel erosion and to further stabilize road and pad surface. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 3/15/2024 4:20:57 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403706380	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files