

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2024

Submitted Date:

03/26/2024

Document Number:

702403233

FIELD INSPECTION FORMLoc ID 318883 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242379	WELL	SI	11/01/2021	OW	123-10170	JOHN HORST B 2	SI

General Comment:[This is a wellsite inspection](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Ancillary equip. has fabricated steel pipe and round stock.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:

Type: Prime Mover	# 1		corrective date
Comment:	electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	electric panel, meter box ,transformers & telemetry		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	242379	Type:	WELL	API Number:	123-10170	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: SI since 11-2021 & last produced 5/2021. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.									
Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.									
Date: 04/26/2024									
BradenHead									
Date of Last Brhd Test: 06/26/2023 Annual Brhd Completed? Yes									
Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____									
End Surf Csg Pressure: 0									
Comment: plumbed to surface									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday 3-26-2024 at approximately 1255 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: This Field Inspection is due to a 901 order. Operator: KP Kauffman</p> <p>Location name:</p> <p>Location ID # 318883</p> <p>Well Name: John Horst B 2</p> <p>API # 05-123-10170</p> <p>County: Weld</p> <p>Weather: Clear</p> <p>Location: Wet, muddy.</p> <p>While there, I observed a wellsite, SI at the time of the inspection.</p> <p>During this inspection, I observed the following possible compliance issues:</p> <p>417.b MIT: Shut In wells, CA date 4-26-2024</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p> <p>Any Corrective Actions from previous inspections not addressed are still applicable.</p>	revasr	03/26/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702403237	location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6482306