

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad
Location ID: 335486



**Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is in close proximity to Rule 411a Surface Water External Buffer.
Section/Township/Range: 36 6S94W**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad
Location ID: 335486



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.