

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403710524

Date Received:  
03/26/2024

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>	<u>(970) 285-9377</u>	<u>COGCCInspectionReports@terraep.com</u>
<u>Wilson, Justin</u>	<u>(970) 878-3825</u>	<u>jrwilson@blm.gov</u>

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 702502028  
Inspection Date: 10/24/2023 FIR Submit Date: 10/25/2023 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**LOCATION** - Location ID: 419254

Location Name: Federal RGU Number: 23-23-198 County: \_\_\_\_\_  
Qtrqtr: NESW Sec: 23 Twp: 1S Range: 98W Meridian: 6  
Latitude: 39.946904 Longitude: -108.362654

**FACILITY** - API Number: 05-103-00 Facility ID: 419254

Facility Name: Federal RGU Number: 23-23-198  
Qtrqtr: NESW Sec: 23 Twp: 1S Range: 98W Meridian: 6  
Latitude: 39.946904 Longitude: -108.362654

**CORRECTIVE ACTIONS:**

1  CA# 185980

Corrective Action: Repair equipment. Clean up containment. Remove and properly dispose of impacted soil. Date: 10/31/2023

Response: CA COMPLETED Date of Completion: 11/21/2023

Operator Comment: Tank leak has been fixed. Stained soil has been removed. Corrective Action complete.

COGCC Decision:

Approved pending re-inspection

COGCC  
Representative:

**2**  CA# 185981

Corrective Action: All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.

Date: 10/24/2023

Response: CA COMPLETED

Date of Completion: 01/17/2024

Operator Comment: Deadman has been properly marked. Corrective Action complete.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA#185980: Tank leak has been fixed. Stained soil has been removed. Corrective Action complete.  
CA#185981: Deadman has been properly marked. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 3/26/2024 4:42:17 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403710524	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files