

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403711016

Date Received:

03/26/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708301084

Inspection Date: 10/17/2023

FIR Submit Date: 10/20/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 324123

Location Name: UNOCAL-66S96W Number: 29SESE County: \_\_\_\_\_

Qtrqr: SESE Sec: 29 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.490628 Longitude: -108.123937

### FACILITY - API Number: 05-045-

-00

Facility ID: 324123

Facility Name: UNOCAL-66S96W

Number: 29SESE

Qtrqr: SESE Sec: 29 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.490628 Longitude: -108.123937

### CORRECTIVE ACTIONS:

1 ☒ CA# 185659

Corrective Action: Cap or install wildlife protection equipment on vent line to comply with Rule 608.a.(13).

Date: 10/25/2023

Response: CA COMPLETED

Date of Completion: 10/26/2023

Operator  
Comment:

Wildlife protection has been installed to the open-ended vent. Corrective Action complete.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 185660

Corrective Action: Remove debris to comply with Rule 606.

Date: 10/27/2023

Response: CA COMPLETED

Date of Completion: 10/26/2023

Operator  
Comment: Debris has been removed from location. Corrective Action complete.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 185661

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 11/04/2023

Response: CA COMPLETED

Date of Completion: 10/26/2023

Operator  
Comment: Pad surface has been bladed/graded and stabilized. Corrective Action complete.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA#185659: Wildlife protection has been installed to the open-ended vent. Corrective Action complete.  
CA#185660: Debris has been removed from location. Corrective Action complete.  
CA#185661: Pad surface has been bladed/graded and stabilized. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 3/26/2024 4:52:19 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

|           |                          |
|-----------|--------------------------|
| 403711016 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

Total Attach: 1 Files