



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	electrical disconnect, metetal panels		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	

**Equipment:**

Type	Quantity	Comment	Corrective Action	Date	corrective date
Prime Mover	# 1	natural gas, no battery			
Pump Jack	# 1				
Ancillary equipment	# 2	electrical disconnect panels			
Bradenhead	# 1	piped to surface			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241008 Type: WELL API Number: 123-08796 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

**Comment:** Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

**Corrective Action:** Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/26/2024

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      Inspector Michael Kester,                      conducted on-site inspection                      Location: Paul W Heinze 2                      Operator: KPK                      API#: 123-08796                      County: Weld                      While there, I observed well site with pumping unit,                      During this inspection, the following possible compliance issues were observed:                      Mechanical integrity Testing, Rule 417b, corrective action date 4-26-2024</p> <p>Weather conditions: sunny and dry                      A follow up on this site inspection needs to be conducted to ensure the                      Compliance issues have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC                      This is a continuing education inspection</p>	kesterm	03/26/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403732371	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6482689">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6482689</a>
713300742	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6482684">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6482684</a>