

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/02/2024

Submitted Date:

04/04/2024

Document Number:

707800876**FIELD INSPECTION FORM**Loc ID 334671 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266898	WELL	PR	08/18/2003	GW	045-09189	GMR 33-9 (P33NWB)	PR
267446	WELL	PR	05/08/2009	GW	045-09199	GMR 33-7D (P33NEB)	PR
267448	WELL	PR	09/04/2003	GW	045-09197	GMR 33-9D (P33NWB)	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday 4/2/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus P33NEB, at Location # 334671 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Location shows light signs of lack of stabilization and no evidence of tracking BMP's
2. Random staining
3. Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks.		
Corrective Action:	Eliminate possibility of wildlife to enter open lines for thawing out dump lines with exhaust from trucks.		Date: 05/09/2024
Type	OTHER		
Comment:	Random staining		
Corrective Action:	Remove stained material		Date: 05/09/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 3		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	bearproof trash bin		
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 6	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 7	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 3	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	266898	Type:	WELL	API Number:	045-09189	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	267446	Type:	WELL	API Number:	045-09199	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	267448	Type:	WELL	API Number:	045-09197	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction in areas
Berms						

Comment: 1. Location shows light signs of lack of stabilization and no evidence of tracking BMP's
Places with sparse to no gravel & light compaction are present on location. Sparse to no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action: Install, maintain or repair required BMPs

Date: 05/16/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800885	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6496927