

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 3		
Comment:	electric/automation panels		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 240863 Type: WELL API Number: 123-08651 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/29/2024

BradenHead

Date of Last Brhd Test: 03/06/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: submit report

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p><u>ECMC Inspection Report Summary</u> <u>Inspector Michael Kester,</u> <u>conducted on-site inspection</u> <u>Location: James S Haley Trustee B 2</u> <u>Operator: KPK</u> <u>API#: 123-08651</u> <u>County: Weld</u> <u>While there, I observed well site with pumping unit,</u> <u>During this inspection, the following possible compliance issues were observed:</u> <u>Mechanical integrity Testing, Rule 417b, corrective action date 4-29-2024</u></p> <p><u>Weather conditions: sunny and dry</u> <u>A follow up on this site inspection needs to be conducted to ensure the</u> <u>Compliance issues have been corrected to comply with ECMC rules.</u> <u>This is a summary of inspection report.</u></p> <p><u>This inspection does not nullify any orders or NOAV from the ECMC</u> <u>This is a continuing education inspection</u></p>	kesterm	03/29/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403737078	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6487975
713300770	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6487972