

RECEIVED

OGCC FORM 4

OIL AND GAS CONSERVATION COMMISSION  
OF THE STATE OF COLORADO

FEB 24 1970

COLO. OIL &amp; GAS CONS. COMM.



00788338

e in duplicate for Patented and Federal lands.  
file in triplicate for State lands.

3. LEASE DESIGNATION AND SERIAL NO.

Fed. Colo. 1266 Acq.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NO

7. UNIT AGREEMENT NAME

NO

8. FARM OR LEASE NAME

Federal C-1266 acq

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

4-9N-56W

12. COUNTY OR PARISH

Weld

13. STATE

Colo.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Braden-Gear Drilling Company

3. ADDRESS OF OPERATOR

470 Denver Club Bldg, Denver, Colo. 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface 660 FNL 665 FWL NW/4

At proposed prod. zone

Same

14. PERMIT NO.

68-57

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4540 KB

4533 GR.

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT ☒(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)

Date of work Feb. 11-14, 1970

Sand to 5915', dumped 5 sax cement to 5885', shot off @ 5100', set 15 sax  
cement plug, pulled casing. Mud hole to 140', 15 sax cement to 95',  
mud to 30', run 10 sax cement to base cellar and welded on cap. Set  
marker

DVR	
FJP	
HHM	<input checked="" type="checkbox"/>
JAM	<input checked="" type="checkbox"/>
LJD	<input checked="" type="checkbox"/>

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DIRECTOR  
CONS. COMM.

FEB 26 1970

after re-entry