

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2024

Submitted Date:

04/16/2024

Document Number:

713300805

FIELD INSPECTION FORMLoc ID 318909 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections
Silver, Randy	720-827-6688	randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242443	WELL	SI	05/01/2021	OW	123-10234	SEBOLD, DOROTHY B-2	SI

General Comment:

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☒

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Date Run: 4/16/2024 Doc [#713300805]

Page 2 of 3

Inspected Facilities

Facility ID: 242443

Type: WELL

API Number: 123-10234

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Follow up inspection to Doc# 713300718 in response to FIRR #403730345. Based on photos submitted by operator corrective actions appear to have been completed.	kesterm	04/16/2024