

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/17/2024

Submitted Date:

04/17/2024

Document Number:

714200943

FIELD INSPECTION FORM

Loc ID 329308 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | Inspections@civiresources.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 249335 | WELL | SI | 11/01/2023 | GW | 123-17137 | FEDERAL 32-10 | TA |

General Comment:

[THIS IS A WELLHEAD INSPECTION.](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| | Type WELLHEAD | | |
| Comment: | incorrect signage displayed. See attached photo. | | |
| Corrective Action: | Comply with Rule 605. | Date: | 04/24/2024 |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | <input style="width: 95%;" type="text"/> | Date: | <input style="width: 95%;" type="text"/> |
| Corrective Action: | <input style="width: 95%;" type="text"/> | | |

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | unused equipment at wellhead. See attached photo. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 04/24/2024 |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------|-----|-------|-----------------|
| | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 249335 Type: WELL API Number: 123-17137 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; equipment removed.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 08/23/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>COGCC Inspection Report Summary WEATHER CONDITIONS: sunny, dry ground On Wednesday, April 17, 2024 at approximately 0945, I, Inspector Brittani Santistevan, conducted an on-site inspection at FEDERAL 32-10 (Crestone Peak Resources Operating, LLC), at location ID: 329308 in WELD COUNTY, Colorado. While there, I observed temporarily abandoned wellhead. During this inspection the following possible compliance issues were observed: 1. It appears signage displays the wrong wellhead name. Comply with Rule 605. (Corrective Action Date: April 24, 2024) See attached photo #2. 2. It appears to be unused/disconnected equipment at wellhead. Re-connect or remove from location to comply with Rule 606. (Corrective Action Date: April 24, 2024) See attached photo 3,4.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | santistb | 04/17/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 714200944 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515855 |