

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403765915

Date Received:

04/23/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10701

Name of Operator: UPLAND EXPLORATION LLC

Address: 424 S MAIN ST

City: BOERNE State: TX Zip: 78006

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Rollins, Dustin dnr_cogccenforcement@state.co.us

Rollins, Dustin dustin@uplandexploration.com

Trujillo, Aaron david@uplandexploration.com

Trujillo, Aaron aaron.trujillo@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 697504601

Inspection Date: 04/07/2023

FIR Submit Date: 04/17/2023

FIR Status: _____

Inspected Operator Information:

Company Name: UPLAND EXPLORATION LLC

Company Number: 10701

Address: 424 S MAIN ST

City: BOERNE State: TX Zip: 78006

LOCATION - Location ID: 462919

Location Name: Little Lady 21 Number: South Well Pad County: _____

Qtrqr: SESE Sec: 21 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.900550 Longitude: -104.542850

FACILITY - API Number: 05-123-00 Facility ID: 462919

Facility Name: Little Lady 21 Number: South Well Pad

Qtrqr: SESE Sec: 21 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.900550 Longitude: -104.542850

CORRECTIVE ACTIONS:

1 CA# 169600

Corrective Action: Comply with Rule 606.c.

Date: 02/10/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 02/10/2023

Operator Comment: 2/28/2023 Dustin Rollins, Upland Field Supervisor met w/Chris Binschus on location to discuss weed management; conversed that the weeds are dormant and spraying needed to start soon. Weed mitigation started 3/1/2023 and All weeds have been removed along the edges of location, along with wellhead area and production/equipment pad area by 3/2/2023. Weed management has been outsourced to Precision Industrial Applicators and will commence on-going services starting 4/11/2023 (weather permitting) and continue throughout the spring/summer until no longer needed. Weeds are be managed. Cereal Rye (seen in later inspections) is a non-native plant - it was not in the seed-mixture utilized by Upland. Cereal rye grasses have been mowed (utilizing a weed whacker) on 8/7, 8/24, 9/24 and 10/24. The areas where cereal rye is present will continue to be addressed by cutting and will be spot sprayed with herbicide.

ECMC Decision: _____

ECMC
Representative:

2 CA# 169601

Corrective Action: Comply with Rule 606.a.

Date: 02/10/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 05/11/2023

Operator Comment: Hoses previously seen in the secondary containment are now properly stored. Later inspections do not state that the hoses are still within the secondary containment.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dustin Rollins

Signed: _____

Title: Field Supervisor

Date: 4/23/2024 12:23:08 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

--	--

Total Attach: 0 Files