

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403615807

Date Received:
12/06/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 52530
Name of Operator: MAGPIE OPERATING INC
Address: 2707 SOUTH COUNTY RD 11
City: LOVELAND State: CO Zip: 80537

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>WARNER, JAMES</u>	<u>970-669-6308</u>	<u>jwarner105@gmail.com</u>
<u>Warner, Ryan</u>	<u>720-233-0875</u>	<u>magpieoil@yahoo.com</u>
<u>Alex Ahmadian</u>		<u>alexander.ahmadian@state.co.us</u>
<u>Warner, Ross</u>	<u>720-309-9380</u>	<u>ross.magpieoil@gmail.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100180
Inspection Date: 11/28/2023 FIR Submit Date: 11/30/2023 FIR Status: _____

Inspected Operator Information:

Company Name: MAGPIE OPERATING INC Company Number: 52530
Address: 2707 SOUTH COUNTY RD 11
City: LOVELAND State: CO Zip: 80537

LOCATION - Location ID: 307116

Location Name: IHNEN-65N68W Number: 31SENE County: _____
Qtrqr: SENE Sec: 31 Twp: 5N Range: 68W Meridian: 6
Latitude: 40.358690 Longitude: -105.042241

FACILITY - API Number: 05-069-00 Facility ID: 307116

Facility Name: IHNEN-65N68W Number: 31SENE
Qtrqr: SENE Sec: 31 Twp: 5N Range: 68W Meridian: 6
Latitude: 40.358690 Longitude: -105.042241

CORRECTIVE ACTIONS:

1 CA# 188748

Corrective Action: The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.

Date: 12/26/2023

Response: CA COMPLETED

Date of Completion: 12/01/2023

Operator Comment: Fencing has been maintained to fully surround excavation.

ECMC Decision: Approved

ECMC Representative:

2 CA# 188749

Corrective Action: Comply with Rule 606.

Date: 12/08/2023

Response: CA COMPLETED

Date of Completion: 12/01/2023

Operator Comment: Unused equipment has been removed from location.

ECMC Decision: Approved

ECMC Representative:

3 CA# 188750

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, per Rule 608.e.

Date: 12/01/2023

Response: CA COMPLETED

Date of Completion: 12/01/2023

Operator Comment: Valves have been secured.

ECMC Decision: Approved

ECMC Representative:

4 CA# 188751

Corrective Action: Install sign to comply with Rule 605

Date: 01/03/2024

Response: CA COMPLETED

Date of Completion: 04/23/2024

Operator Comment: Rule 605 does not require signs to be located at excavation projects. A sign is located at the entrance to location, as per 605.a

ECMC Decision: Approved

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Donahue Signed:

Title: Compliance Specialist Date: 12/6/2023 2:23:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403615807	FIR RESOLUTION SUBMITTED
403615810	Photos

Total Attach: 2 Files