

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403766688

Date Received:  
04/23/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 701900943

Inspection Date: 07/01/2023

FIR Submit Date: 07/18/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

### LOCATION - Location ID: 310546

Location Name: BUTTERBALL-63N64W Number: 19SWSW County: \_\_\_\_\_

Qtrqtr: SWS Sec: 19 Twp: 3N Range: 64W Meridian: 6  
W

Latitude: 40.207030 Longitude: -104.602000

### FACILITY - API Number: 05-123-00 Facility ID: 310546

Facility Name: BUTTERBALL-63N64W Number: 19SWSW

Qtrqtr: SWS Sec: 19 Twp: 3N Range: 64W Meridian: 6  
W

Latitude: 40.207030 Longitude: -104.602000

### CORRECTIVE ACTIONS:

1 ☒ CA# 175934

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 07/01/2023

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 04/22/2024

Operator Comment: Stripped roadbase on the facility brought in topsoil, seeded and straw crimped the facility. CA complete.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Stripped roadbase on the facility brought in topsoil, seeded and straw crimped the facility. CA complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed: \_\_\_\_\_

Title: H&S Specialist-Operations

Date: 4/23/2024 3:09:22 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403766688	FIR RESOLUTION SUBMITTED
403766709	1
403766712	2
403766718	3
403766720	4

Total Attach: 5 Files