

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403767618

Date Received:  
04/24/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:  
3 of 3 CAs from the FIR responded to on this Form  
3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10755  
Name of Operator: MORNINGSTAR OPERATING LLC  
Address: 400 W 7TH ST  
City: FORT WORTH State: TX Zip: 76102  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Amy Byars</u>	<u>817-334-8096</u>	<u>abyars@mspartner.com</u>
<u>Connie Blaylock</u>	<u>817-334-7882</u>	<u>cblaylock@mspartner.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000674  
Inspection Date: 04/12/2024 FIR Submit Date: 04/16/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: MORNINGSTAR OPERATING LLC Company Number: 10755  
Address: 400 W 7TH ST  
City: FORT WORTH State: TX Zip: 76102

LOCATION - Location ID: 333343

Location Name: PETERSON 32-6-N32N6W Number: 14SESW County: \_\_\_\_\_  
Qtrqtr: SESW Sec: 14 Twp: 32N Range: 6W Meridian: N  
Latitude: 37.013660 Longitude: -107.470390

FACILITY - API Number: 05-007-00 Facility ID: 333343

Facility Name: PETERSON 32-6-N32N6W Number: 14SESW  
Qtrqtr: SESW Sec: 14 Twp: 32N Range: 6W Meridian: N  
Latitude: 37.013660 Longitude: -107.470390

CORRECTIVE ACTIONS:

**1** CA# 194296

Corrective Action: Comply with rule 606, remove and properly dispose of debris. Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 04/23/2024

Operator Comment: Debris removed 4/23

ECMC Decision: \_\_\_\_\_

ECMC Representative:

2 CA# 194297

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.

Date: 04/22/2024

Response: CA COMPLETED

Date of Completion: 04/23/2024

Operator Comment: Equipment has been cleaned

ECMC Decision:

ECMC Representative:

3 CA# 194298

Corrective Action: comply with rule 608a Install or repair wildlife protection equipment.

Date: 04/22/2024

Response: CA COMPLETED

Date of Completion: 04/23/2024

Operator Comment: Wildlife protection equipment has been repaired.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: As of 4/23, debris has been removed, equipment cleaned up, and wildlife protection equipment repaired.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock

Signed:

Title: Regulatory Analyst

Date: 4/24/2024 11:07:18 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (http://ecmcweblink.state.co.us/) - Search by Document Number.

Table with 2 columns: Document Number, Description. Rows include photo numbers and descriptions of debris removal and wildlife protection repairs.

Total Attach: 6 Files