



99999999

DO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	
API No. 05- <u>123 - 05318</u>	LEASE NAME: <u>Fred Brunner #2</u>
LOCATION: <u>NESW-526-7N-67W</u>	OPERATOR: <u>Chevron U.S.A.</u>
DATE: <u>2/12/98</u>	INSPECTOR: <u>Paul Ke</u>
Insp. Type: <u>HR</u>	Insp. Status: <u>PA</u>
PA: <u>Y</u> N	Pass/Fail: <u>P</u> F
Viol.: <u>Y</u> N	NOV: <u>Y</u> N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))		
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous		

RECEIVED
 MAR - 6 98
 COGCC



CORRECTIVE ACTION REQUIRED: No surface disturbance found

Date Corrective Action Required By: _____ Date Remedied: _____

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.