

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2024

Submitted Date:

04/26/2024

Document Number:

702502656

## FIELD INSPECTION FORM

 Loc ID 314518 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 ECMC Operator Number: 16700  
 Name of Operator: CHEVRON USA INC  
 Address: 760 HORIZON DRIVE STE 401  
 City: GRAND JUNCTION State: CO Zip: 81506
**Contact Information:**

Contact Name	Phone	Email	Comment
Olson, Andrew		andrewolson@chevron.com	
WHITE, JEFFERY		jeffery.white@chevron.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
, Inspections		rbucogccinspectionreports@chevron.com	

**General Comment:**[ECMC Inspection Report Summary](#)

On Friday, 04/26/2024, Inspector Kirby Burchett, submitted a follow up inspection for Chevron USA Inc on the Wilson Creek Unit 25 well, Location #314518, in Rio Blanco County, Colorado.

This location is within or close proximity to a Parks & Wildlife (CPW) District with High Priority, NSO, Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up on Corrective Action issued during Inspection #702502608 on 4/16/24 for No Form 6 – Subsequent Report of Abandonment. Operator responded with FIRR #403758180 indicating that a Form 6 had been filed on 9/18/23, Document #403533130. Document is in the system resulting in Corrective Action being resolved.

No follow up inspection is required.