


Fram Bond Claim: Task 2 - Plug and Abandon, Flowline Abandonment, Equipment Salvage - 322010 029-06100
HAMILTON #33-2

Prepared SRC 12/9/2022 **Notes:**
Spud 11/17/2006

FIELD NAME Wildcat
FIELD NUMBER 99999

LOCATION

Basin Piceance Mineral Owner: Fee
Location-Townships 13S Surface Owner: Fee
Location-Ranges 95W
Elevation 5,656'



Space	Hole/Csg	Csg	cf/f	bbls/ft
Annulus above shoe				
Annulus below shoe				
Casing	0	5.5	0.1650	0.0294
Plug #	sx	bbls		
1		3	0.6	
2		20	3.9	
3		10	2.0	
Total		33	6.5	

*BOP or other mechanical method should be used for well control

