


Fram Bond Claim: Task 2 - Plug and Abandon, Flowline Abandonment, Equipment Salvage - 334484 077-08886
EBERLY #23-4

Prepared SRC 12/10/2022 **Notes:**
Spud 06/06/2005

FIELD NAME Wildcat
FIELD NUMBER 99999

LOCATION

Basin Piceance Mineral Owner: Fee
Location-Townships 2S Surface Owner: Fee
Location-Ranges 2E
Elevation 5,556'



Space	Hole/Csg	Csg	cf/f	bbls/ft
Annulus above shoe	7	4.5	0.1106	0.0197
Annulus below shoe	6.125	4.5	0.0942	0.0168
Casing	0	4.5	0.0896	0.0159

Plug #	sx	bbls
1	2	0.4
2	70	13.7

Total	72	14
-------	----	----

*BOP or other mechanical method should be used for well control

