

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403774390

Date Received:

04/30/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name:

Phone: ( ) Fax: ( )

Email:

#### Additional Operator Contact:

Contact Name

Phone

Email

-

[rbucogccinspectionreports@chevron.onmicrosoft.com](mailto:rbucogccinspectionreports@chevron.onmicrosoft.com)

### ECMC INSPECTION SUMMARY:

FIR Document Number: 697602332

Inspection Date: 04/17/2024

FIR Submit Date: 04/25/2024

FIR Status:

#### Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

#### LOCATION - Location ID: 302480

Location Name: SANDAU K-64N66W

Number: 21SWSE

County:

Qtrqtr: SWSE Sec: 21

Twp: 4N

Range: 66W

Meridian: 6

Latitude: 40.292145

Longitude: -104.777899

#### FACILITY - API Number: 05-123-

-00

Facility ID: 485804

Facility Name: Sandau K21-23 Tank Battery

Number:

Qtrqtr: SWSE Sec: 21

Twp: 4N

Range: 66W

Meridian: 6

Latitude: 40.292145

Longitude: -104.777899

### CORRECTIVE ACTIONS:

1 CA# 194704

Corrective Action: Operator shall immediately submit a Form 27 for Spill ID 485804 that includes a specific workplan and timeline to address the remaining impacts.

Date: 04/01/2024

Response: CA COMPLETED

Date of Completion: 04/29/2024

Operator  
Comment:

Yesterday morning, Tasman submitted a Second Quarter 2024 timeline update on Form 27 document number 403745056 since the site investigation has not been completed. As of this morning, the Form 27 that Tasman submitted yesterday has been returned to draft. When Tasman resubmits the returned to draft form, we will reattach our proposed investigation map for the ECMC. Please let me know if you need any additional information.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 194705

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes in accordance with Rule 1002.f.(2).D

Date: 04/30/2024

Response: CA COMPLETED

Date of Completion: 04/27/2024

Operator  
Comment: Complied with Rule 1002.f(2).D.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Completed both Corrective Actions.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff White

Signed: \_\_\_\_\_

Title: HSE

Date: 4/30/2024 1:46:52 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403774402	photo
403774403	photo

Total Attach: 2 Files