

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2024

Submitted Date:

05/02/2024

Document Number:

713600989

**FIELD INSPECTION FORM**Loc ID 380504 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10017

Name of Operator: CHACO ENERGY COMPANY

Address: P O BOX 1587

City: DENVER State: CO Zip: 80201

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Nelson, Matt	303-981-3840	matt@chacoenergy.com	
Nelson, Kurt	(303)744-2034	kurt@chacoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
380504	LOCATION	AC			-	Champlin 360 Amoco A 4	CI

**General Comment:**

This is a Construction Inspection at the CHAMPLIN 360 AMOCO A #4 location.

**Location Construction**

Location ID: 207566 CDP: \_\_\_\_\_

**Comment:** Topsoil was not adequately salvaged or protected. Soils are heavily compacted along the access road and at the location. There are minimal topsoil piles which are not stabilized or protected. It appears drilling has been completed and if additional production equipment will be installed then more topsoil will need to be removed and stockpiled. Otherwise, topsoil will need to be properly decompacted and replaced.

**Corrective Action:** Comply with 1002. b rules for soil removal and segregation.  
Comply with 1002.c

**Date:** 05/09/2024**Form 2A COAs:**

**Comment:** There is no netting at the open top tank to prevent wildlife entry. Netting needs to be installed or tank needs to be removed by the CA date.

**Corrective Action:** Comply with 902.b. Install or repair wildlife protection equipment.

**Date:** 05/06/2024**Wildlife BMPs:**

**Comment:** BMP's are insufficient or have not been implemented.

**Corrective Action:** \_\_\_\_\_**Date:** \_\_\_\_\_**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

WADDLES	No	Material Handling And Spill Prevention	No
Comments: Erosion BMPs: <span style="color: red;">There are insufficient BMP's installed at the location. There are no perimeter stormwater controls and the soils are not protected from wind erosion.</span>			
Other BMPs: <span style="color: red;">There is stained soil underneath the backhoe which must be cleaned up.</span>			
Corrective Action: <span style="color: red;">Install or repair required BMPs per Rule 1002.f.(2) Implement or modify BMPs for improved material handling and spill prevention.</span>			Date: 05/06/2024

**Comment:**

**Corrective Action:**

**Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill: DRILLING FLUIDS

Estimated Spill Volume:

Comment: There are stained soils by the open top tank that need to be cleaned up.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 05/06/2024

Reportable: NO

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:

Owner Name:

GPS :

Lat

Long

Field Parameters:

Sample Location:

Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600990	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6533412">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6533412</a>