

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403773384

Date Received:

04/30/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

. General

SJBcompliance@arkomaops.com

Price, Andrew

918-260-8324

aprice@arkomaops.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000652

Inspection Date: 04/05/2024

FIR Submit Date: 04/09/2024

FIR Status: _____

Inspected Operator Information:

Company Name: ARKOMA OPERATIONS LLC

Company Number: 10766

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 311911

Location Name: HAHN-N33N8W Number: 15SESW County: _____

Qtrqtr: SESW Sec: 15 Twp: 33N Range: 8W Meridian: N

Latitude: 37.099730 Longitude: -107.708610

FACILITY - API Number: 05-067- -00 Facility ID: 311911

Facility Name: HAHN-N33N8W Number: 15SESW

Qtrqtr: SESW Sec: 15 Twp: 33N Range: 8W Meridian: N

Latitude: 37.099730 Longitude: -107.708610

CORRECTIVE ACTIONS:

1 ☒ CA# 194135

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 04/16/2024

Response: CA COMPLETED

Date of Completion: 04/29/2024

Operator
Comment:

Weedy Kochis debris has been removed and desposed of.

ECMC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.



Date: 04/16/2024

Date of Completion: 04/29/2024

Strom water wattles have been reset and replaced.

Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

See attached remedial report.

Signed:

Date: 4/30/2024 7:26:22 AM

<u>Document Number</u>	<u>Description</u>
403773384	FIR RESOLUTION SUBMITTED
403773393	Hahn 1A, IGE 100 and IGE 135 Remedial Report (714000652)

Page 2 of 2