


FORM 6 Rev 11/20	State of Colorado Energy & Carbon Management Commission				DE	ET	OE	ES																																	
	1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109				Replug By Other Operator																																				
WELL ABANDONMENT REPORT					Document Number: 403778446																																				
<p>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</p>					Date Received:																																				
ECMC Operator Number: 10459					Contact Name: Derek Clark																																				
Name of Operator: EXTRACTION OIL & GAS INC					Phone: (720) 270-4921																																				
Address: 555 17TH STREET SUITE 3700					Fax:																																				
City: DENVER State: CO Zip: 80202					Email: Declark@civiresources.com																																				
For "Intent" 24 hour notice required, Name: Petrie, Erica Tel: (303) 726-3822																																									
ECMC contact: Email: erica.petrie@state.co.us																																									
Type of Well Abandonment Report: <input checked="" type="checkbox"/> Notice of Intent to Abandon <input type="checkbox"/> Subsequent Report of Abandonment																																									
API Number 05-123-22590-00					Well Number: 1 (OWP)																																				
Well Name: CHINOOK																																									
Location: QtrQtr: NWNW Section: 14 Township: 7N Range: 57W Meridian: 6																																									
County: WELD Federal, Indian or State Lease Number:																																									
Field Name: ENIGMA Field Number: 21600																																									
Only Complete the Following Background Information for Intent to Abandon																																									
Latitude: 40.579247 Longitude: -103.731857																																									
GPS Data: GPS Quality Value: 3.3 Type of GPS Quality Value: Date of Measurement: 10/26/2010																																									
Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems																																									
<input checked="" type="checkbox"/> Other P&A Orphan Well																																									
Casing to be pulled: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Estimated Depth: 3000																																									
Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, explain details below																																									
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, explain details below																																									
Details:																																									
Current and Previously Abandoned Zones																																									
<table><tr><th>Formation</th><th>Perf. Top</th><th>Perf. Btm</th><th>Abandoned Date</th><th>Method of Isolation</th><th>Plug Depth</th></tr><tr><td>J SAND</td><td>6270</td><td>6274</td><td>01/29/2005</td><td>B PLUG CEMENT TOP</td><td>6160</td></tr></table>									Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth	J SAND	6270	6274	01/29/2005	B PLUG CEMENT TOP	6160																					
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																																				
J SAND	6270	6274	01/29/2005	B PLUG CEMENT TOP	6160																																				
Total: 1 zone(s)																																									
Casing History																																									
<table><tr><th>Casing Type</th><th>Size of Hole</th><th>Size of Casing</th><th>Grade</th><th>Wt/Ft</th><th>Csg/Liner Top</th><th>Setting Depth</th><th>Sacks Cmt</th><th>Cmt Btm</th><th>Cmt Top</th><th>Status</th></tr><tr><td>SURF</td><td>11+7/8</td><td>8+5/8</td><td>N/A</td><td>26</td><td>0</td><td>277</td><td>235</td><td>277</td><td>0</td><td>CALC</td></tr><tr><td>1ST</td><td>7+7/8</td><td>5+1/2</td><td>N/A</td><td>15.5</td><td>0</td><td>6170</td><td>230</td><td>6371</td><td>4484</td><td>CBL</td></tr></table>									Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status	SURF	11+7/8	8+5/8	N/A	26	0	277	235	277	0	CALC	1ST	7+7/8	5+1/2	N/A	15.5	0	6170	230	6371	4484	CBL
Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status																															
SURF	11+7/8	8+5/8	N/A	26	0	277	235	277	0	CALC																															
1ST	7+7/8	5+1/2	N/A	15.5	0	6170	230	6371	4484	CBL																															

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 5100 with 4 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 87 sks cmt from 3100 ft. to 2800 ft. Plug Type: STUB PLUG Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 120 sacks half in. half out surface casing from 377 ft. to 0 ft. Plug Tagged: ☐

Set 10 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: _____ Cut and Cap Date: _____ Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____

*Wireline Contractor: _____

*Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

- Notify OWP Supervisor. This well will be plugged per Civitas' Agreement for Plugging Operations, dated October, 17th, 2022
- Proposed Wellbore Diagram Attached
- CPW consult is not required for big game HPH
- Unable to confirm csg grade with historical documentation, (Used NA).

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Ashley Noonan

Title: Sr. Regulatory Analyst

Date: _____

Email: regulatory@civiresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

Expiration Date: _____

<u>COA Type</u>	<u>Description</u>
0 COA	

ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
403778537	WELLBORE DIAGRAM

Total Attach: 1 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)