

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403236984

Date Received:  
11/22/2022

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

. General

sjninspections@ikavenergy.com

Labowskie, Steve

steve.labowskie@state.co.us

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 702500530

Inspection Date: 09/30/2022

FIR Submit Date: 09/30/2022

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**LOCATION** - Location ID: 334264

Location Name: FRENCH-M34N7W Number: 9NWNW County: LA PLATA

Qtrqtr: NWN Sec: 9 Twp: 34N Range: 7W Meridian: M  
W

Latitude: 37.210604 Longitude: -107.618797

**FACILITY** - API Number: 05-067-00 Facility ID: 214958

Facility Name: FRENCH Number: 01-9U 1

Qtrqtr: NWN Sec: 9 Twp: 34N Range: 7W Meridian: M  
W

Latitude: 37.210604 Longitude: -107.618797

**CORRECTIVE ACTIONS:**

1 CA# 164895

Corrective Action: Repair berms or other secondary containment devices per Rule 912.d.(1).

Date: 10/22/2022

Response: CA COMPLETED

Date of Completion: 10/25/2022

Operator Comment: Berm height repaired around secondary containment.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

\_\_\_\_\_

**2** CA# 164896

Corrective Action: Ensure within 25' of wellhead, tanks, and separators are free of combustibile material per rule 610.k

Date: 10/08/2022

Response: CA COMPLETED

Date of Completion: 10/21/2022

Operator Comment: Mechanical removal of weeds around pumpjack and water tank equipment.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

\_\_\_\_\_

**3** CA# 164897

Corrective Action: All unused equipment must be stored off location per rule 606.

Date: 10/15/2022

Response: CA COMPLETED

Date of Completion: 10/25/2022

Operator Comment: Equipment (traffic cones/sign/mini excavator removed from location.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

\_\_\_\_\_

**4** CA# 164898

Corrective Action: Remove equipment per rule 606.

Date: 11/30/2022

Response: CA COMPLETED

Date of Completion: 10/25/2022

Operator Comment: Equipment (traffic cones/sign/mini excavator removed from location.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

\_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: CA complete. See attached photos.

\_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: \_\_\_\_\_

Title: Permitting Specialist I

Date: 11/22/2022 8:51:22 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403236984	FIR RESOLUTION SUBMITTED
403236992	French 01-9U 1, CA Complete Photos - Weeds
403236993	French 01-9U 1, CA Complete Photos

Total Attach: 3 Files