

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403447703

Date Received:
06/28/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

11 of 11 CAs from the FIR responded to on this Form

11 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 7125
Name of Operator: BEEMAN OIL & GAS INC
Address: 13635 E 104TH AVENUE STE 400
City: COMMERCE CITY State: CO Zip: 80022

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Pate, James</u>		<u>jspconcrete@yahoo.com</u>
<u>Cassey Swaysey</u>		<u>cassyswasey@gmail.com</u>
<u>Galloway, Kelly</u>		<u>kgallowaywerc@gmail.com</u>
<u>Stepp, Sarah</u>		<u>wcciassistant@gmail.com</u>
		<u>dnr_cogccenforcement@state.co.us</u>
<u>Arthur, Denise</u>		<u>denise.arthur@state.co.us</u>
<u>Trujillo, Aaron</u>		<u>aaron.trujillo@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 702801508
Inspection Date: 05/08/2023 FIR Submit Date: 05/09/2023 FIR Status: _____

Inspected Operator Information:

Company Name: BEEMAN OIL & GAS INC Company Number: 7125
Address: 3401 QUEBEC ST SUITE 9105
City: DENVER State: CO Zip: 80207

LOCATION - Location ID: 425419

Location Name: Bret Grandbouche Number: 24-02H County: _____
Qtrqtr: SESW Sec: 2 Twp: 6N Range: 92W Meridian: 6
Latitude: 40.494389 Longitude: -107.689272

FACILITY - API Number: 05-081-00 Facility ID: 425419

Facility Name: Bret Grandbouche Number: 24-02H
Qtrqtr: SESW Sec: 2 Twp: 6N Range: 92W Meridian: 6
Latitude: 40.494389 Longitude: -107.689272

CORRECTIVE ACTIONS:

1 CA# 170745

Corrective Action: Install sign to comply with Rule 605.d.

Date: 07/08/2023

Response: CA COMPLETED

Date of Completion: 06/28/2023

Operator Comment: sign is on order and will be installed asap

ECMC Decision:

ECMC Representative:

2 CA# 170746

Corrective Action: Remove unused equipment or reinstall pipe. Install or repair wildlife protection BMPs to ensure wildlife cannot enter the pipe opening.

Date: 05/14/2023

Response: CA COMPLETED

Date of Completion: 05/13/2023

Operator Comment: Pipe has been removed

ECMC Decision:

ECMC Representative:

3 CA# 170747

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention to prevent a spill and ensure the tank stand is secured and does not tip over.

Date: 05/14/2023

Response: CA COMPLETED

Date of Completion: 05/13/2023

Operator Comment: stand has been uprighted and secured.

ECMC Decision:

ECMC Representative:

4 CA# 170748

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention to prevent a spill from the methanol tank secondary containment device.

Date: 05/14/2023

Response: CA COMPLETED

Date of Completion: 05/13/2023

Operator Comment: BMPs corrected

ECMC Decision:

ECMC Representative:

5 CA# 170749

Corrective Action: Provide proper labeling.

Date: 06/08/2023

Response: CA COMPLETED

Date of Completion: 06/28/2023

Operator Comment: new labels placed

ECMC Decision: _____

ECMC
Representative:

6 CA# 170750

Corrective Action: Date: 12/21/2022

Response: CA COMPLETED

Date of Completion: 06/27/2023

Operator
Comment:

ECMC Decision: _____

ECMC
Representative:

7 CA# 170751

Corrective Action: Date: 05/19/2023

Response: CA COMPLETED

Date of Completion: 05/19/2023

Operator
Comment:

ECMC Decision: _____

ECMC
Representative:

8 CA# 170752

Corrective Action: Date: 06/28/2019

Response: CA COMPLETED

Date of Completion: 05/12/2023

Operator
Comment:

ECMC Decision: _____

ECMC
Representative:

9 CA# 170753

Corrective Action: Date: 11/28/2022

Response: CA COMPLETED

Date of Completion: 06/28/2023

Operator
Comment:

ECMC Decision: _____

ECMC
Representative:

10 CA# 170754

Corrective Action:

Date: 06/29/2012

CA #1: Comply with 1003 Rules. Conduct interim reclamation on the Location including, but not limited to: gravel removal, compaction alleviation (cross ripping to a minimum depth of 18 inches), recontouring/regrading, replacement of topsoil, and revegetation activities; use a seed mixture provided by the surface owner, or a mixture prescribed by the local soil conservation district. Implement control measures to stabilize the seeded soil in accordance with Rule 1002.f.(2)C. CA date: 06/29/2012.

CA #2: Comply with Rule 1003.f; conduct weed management on the Location. This corrective action is subject to NOAV #403368220. No CA date is being provided as Operator is directed to perform the corrective action immediately.

Response: CA COMPLETED

Date of Completion: 06/23/2023

Operator Comment: the location has been shrunk, gravel stockpiled, topsoil replaced, seeded, crimped the soil. All weeds have been sprayed and will be sprayed again

ECMC Decision:

ECMC Representative:

11 CA# 170755

Corrective Action: Comply with Rule 1002.f.(2) and implement and maintain BMPs in accordance with good engineering practices to stabilize the cut slopes, as well as to minimize erosion, degradation, and transport of sediment offsite. This corrective action is subject to NOAV #403368220. No CA date is being provided as Operator is directed to perform the corrective action immediately.

Date:

Response: CA COMPLETED

Date of Completion: 06/27/2023

Operator Comment: changed the slopes of the banks, seeded, crimped the soil

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All items have been addressed. New sign is on order and will be placed as soon as it arrives.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lisa Lawton

Signed:

Title: AGENT

Date: 6/28/2023 11:59:29 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403447703	FIR RESOLUTION SUBMITTED
403447763	Stand upright and secured, location
403447767	reclamation
403447768	weed spraying
403447770	weed spraying
403447771	weed spraying

403447772	weed spraying
403447773	reclamation, bmps of crimping, seeded
403447775	reclamation, soil crimping, seeded, changed slopes

Total Attach: 9 Files