

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
402668868

Date Received:  
04/27/2021

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10679  
Name of Operator: LOGOS OPERATING LLC  
Address: 2010 AFTON PLACE  
City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Roy, Catherine</u>		<u>catherine.roy@state.co.us</u>
<u>Trujillo, Etta</u>		<u>etrujillo@logosresourcesllc.com</u>
<u>Florez, Marie</u>		<u>mflorez@logosresourcesllc.com</u>
<u>Rowley, Darren</u>	<u>505-947-4974</u>	<u>drowley@logosresourcesllc.com</u>
<u>Sessions, Tamara</u>	<u>505-324-4145</u>	<u>tsessions@logosresourcesllc.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 700300130  
Inspection Date: 04/09/2021 FIR Submit Date: 04/16/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC Company Number: 10679  
Address: 2010 AFTON PLACE  
City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 325162

Location Name: BONDAD 33-9-N33N9W Number: 8SWNW County: LA PLATA  
Qtrqtr: SWN Sec: 8 Twp: 33N Range: 9W Meridian: N  
W  
Latitude: 37.121570 Longitude: -107.854960

FACILITY - API Number: 05-067- -00 Facility ID: 214169

Facility Name: BONDAD 33-9 Number: 25  
Qtrqtr: SWN Sec: 8 Twp: 33N Range: 9W Meridian: N  
W  
Latitude: 37.121570 Longitude: -107.854960

CORRECTIVE ACTIONS:

**1** CA# 149693

Corrective Action: use or remove, submit Form 44 as necessary

Date: 05/16/2021

Response: CA COMPLETED

Date of Completion: 04/23/2021

Operator Comment: The equipment belonging to the landowner including a fuel pot assembly, regulator, valves and gauge for their disconnected domestic tap was removed on 4-23-2021. No Form 44 required.

ECMC Decision:

ECMC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: The equipment belonging to the landowner including a fuel pot assembly, regulator, valves and gauge for their disconnected domestic tap was removed on 4-23-2021. No Form 44 required.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tamra Sessions

Signed:

Title: Regulatory Specialist

Date: 4/27/2021 3:58:16 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402668868	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files