

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403633567

Date Received:

03/04/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Heibel, Krystal

krystal.heibel@state.co.us

Bongers, Brent

361-935-5633

bbongers@impetroresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 701603756

Inspection Date: 07/25/2023

FIR Submit Date: 07/27/2023

FIR Status: _____

Inspected Operator Information:

Company Name: WARD & SON* ALFRED

Company Number: 94300

Address: P O BOX 737

City: OGALLALLA State: NE Zip: 69153

LOCATION - Location ID: 312311

Location Name: STATE-611N53W Number: 23NENW County: LOGAN

Qtrqtr: NENW Sec: 23 Twp: 11N Range: 53W Meridian: 6

Latitude: 40.918714 Longitude: -103.259437

FACILITY - API Number: 05-075- -00 Facility ID: 221186

Facility Name: STATE Number: 6

Qtrqtr: NENW Sec: 23 Twp: 11N Range: 53W Meridian: 6

Latitude: 40.918714 Longitude: -103.259437

CORRECTIVE ACTIONS:

1 CA# 176532

Corrective Action: COMPLY WITH RULE 900 SERIES

Date: 07/29/2023

Response: CA COMPLETED

Date of Completion: 07/29/2023

Operator
Comment:

Saturated Soils at PJ Gear Box and inside the shed have been properly removed and disposed of per Rule 900 series.

ECMC Decision: _____

ECMC
Representative:

2 CA# 176533

Corrective Action: COMPLY WITH RULE 606

Date: 08/03/2023

Response: CA COMPLETED

Date of Completion: 08/23/2023

Operator
Comment: Debris has been removed from location per Rule 606.

ECMC Decision:

ECMC
Representative:

3 CA# 176534

Corrective Action: COMPLY WITH RULE 605 SERIES

Date: 09/27/2023

Response: CA COMPLETED

Date of Completion: 09/27/2023

Operator
Comment: Updated sign with identifying current Owner/Operator per Rule 605 series.

ECMC Decision:

ECMC
Representative:

4 CA# 176535

Corrective Action: COMPLY WITH RULE 606

Date: 08/03/2023

Response: CA COMPLETED

Date of Completion: 08/03/2023

Operator
Comment: Weeds have been mowed and are being maintained per Rule 606.

ECMC Decision:

ECMC
Representative:

5 CA# 176536

Corrective Action: COMPLY WITH RULE 605 SERIES

Date: 08/27/2023

Response: CA COMPLETED

Date of Completion: 08/27/2023

Operator
Comment: Per Rule 605, current emergency number on signage has been added to signage.

ECMC Decision:

ECMC
Representative:

6 CA# 176537

Corrective Action: COMPLY WITH RULE 906

Date: 07/30/2023

Response: CA COMPLETED

Date of Completion: 07/30/2023

Per Rule 906, stained soils at the pumpjack have been removed and properly disposed of.

Comment:

Corrective actions were done by due dates. FIRR submittal was waiting on the requested photos for documentation.

Print Name: Amber Barnett

Signed:

Title: Compliance Specialist

Date: 3/4/2024 3:34:20 PM

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403633567	FIR RESOLUTION SUBMITTED
403707215	Photo Log

Date Run: 5/4/2024 Doc [#403633567]