

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403785477

Date Received:

05/09/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Jones, Tammy</u>		<u>FarmingtonRegulatoryTechs@hilcorp.com</u>
<u>Shorty, Priscilla</u>	<u>505-324-5188</u>	<u>pshorty@hilcorp.com</u>
<u>Walker, Mandi</u>		<u>mwalker@hilcorp.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000509

Inspection Date: 03/06/2024

FIR Submit Date: 03/07/2024

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326452

Location Name: ARGENTA 33-10-N33N10W Number: 3SEnw County: _____

Qtrqtr: SEnw Sec: 3 Twp: 33N Range: 10W Meridian: N

Latitude: 37.136037 Longitude: -107.924110

FACILITY - API Number: 05-067- -00 Facility ID: 326452

Facility Name: ARGENTA 33-10-N33N10W Number: 3SEnw

Qtrqtr: SEnw Sec: 3 Twp: 33N Range: 10W Meridian: N

Latitude: 37.136037 Longitude: -107.924110

CORRECTIVE ACTIONS:

1 ☒ CA# 192750

Corrective Action: Comply with rule 606.

Date: 03/22/2024

Response: CA COMPLETED

Date of Completion: 05/09/2024

Operator Comment: Unused oil and gas equipment has been removed.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

2 ☒ CA# 192751

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 03/14/2024

Response: CA COMPLETED

Date of Completion: 05/09/2024

Operator Comment: Weedy debris have been removed.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

3 ☒ CA# 192752

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Date: _____

Response: CA COMPLETED

Date of Completion: 05/09/2024

Operator Comment: Rutting and erosion issues have been resolved.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached RESOVLED PHOTOS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones

Signed: _____

Title: Ops/Regulatory Tech

Date: 5/9/2024 1:40:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403785477	FIR RESOLUTION SUBMITTED
403785478	Resolved Photos

Total Attach: 2 Files