

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403748130

Date Received:

05/14/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Kellerby, Shaun

shaun.kellerby@state.co.us

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708900261

Inspection Date: 04/11/2023

FIR Submit Date: 04/11/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335213

Location Name: CLOUGH-66S94W Number: 21NWSW County: GARFIELD

Qtrqr: NWS Sec: 21 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.510212 Longitude: -107.898743

FACILITY - API Number: 05-045-00 Facility ID: 211589

Facility Name: CLOUGH Number: RMV 217-21

Qtrqr: NWS Sec: 21 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.510212 Longitude: -107.898743

CORRECTIVE ACTIONS:

2 CA# 169269

Corrective Action: Remove and properly dispose of all stained soils and gravel.

Date: 04/21/2023

Response: CA COMPLETED

Date of Completion: 04/17/2023

Operator
Comment:

Stained soil and gravel have been properly removed from location. Corrective Action Completed.

ECMC Decision: _____

ECMC
Representative:

3 CA# 169270

Corrective Action: All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.

Date: 04/25/2023

Response: CA COMPLETED

Date of Completion: 04/17/2023

Operator
Comment:

Deadman anchor has been properly marked. Corrective Action Complete.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA: #169269 - Stained soil and gravel have been properly removed from location. Corrective Action Complete.
CA: #169270 - Deadman anchor has been properly marked. Corrective Action Complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 5/14/2024 1:30:06 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files