

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2024

Submitted Date:

05/08/2024

Document Number:

699505777

FIELD INSPECTION FORM

Loc ID: 318344 Inspector Name: MEDINA, JUSTIN On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241143	WELL	SI	04/01/2021	OW	123-08931	YOXALL FARMS 5	SI

General Comment:

Empty text area for general comments.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: wellhead sign is missing on well.

Corrective Action: Install sign to comply with Rule 605.d.

Date: 06/08/2024

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Bradenhead # 1

Comment: plumbed to surface

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment:

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: electric motor

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 241143 Type: WELL API Number: 123-08931 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/27/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On 5/8/24 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Yoxall Farms 5 Company Name- KPK API- 05-123-08931 In Weld County Colorado. While there, I observed SI well During this inspection the following possible compliance issues were observed: Wellhead sign missing. Rule 605 d. 6/8/24 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	05/08/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505778	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6547860