

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2024

Submitted Date:

05/16/2024

Document Number:

713601029

### FIELD INSPECTION FORM

Loc ID 324809 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 95620  
 Name of Operator: WESTERN OPERATING COMPANY  
 Address: 1165 DELAWARE STREET #200  
 City: DENVER State: CO Zip: 80204

**Findings:**

- 4 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Dale	719-688-1638	dale@westernoperating.com	
James, Steven	(303) 893-2438	steve@westernoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212814	WELL	PR	08/01/2022	OW	061-06174	BUTLER USA 1-X	RI

**General Comment:**

This is a follow up of the previous inspections (#713600596, #713600787).  
 The previous corrective actions have not been completed and will be referred to enforcement.  
 Operator is directed to perform corrective actions outlined on this inspection report immediately.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	H2S wind sock has been replaced.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	There are two unused large volumes tanks stored on the location and unused tanks parts near the powerpole that need to be removed. Previous corrective action has not been completed.		
Corrective Action:	Comply with Rule 606.	Date:	
Type	OTHER		
Comment:	There is a hatch opened at the backside of the tank which could entrap wildlife and must be covered.		
Corrective Action:	Comply with 902.b. and install wildlife protection.	Date:	05/23/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601030	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6550027">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6550027</a>