

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2024

Submitted Date:

05/16/2024

Document Number:

699700370

FIELD INSPECTION FORM

Loc ID 323896 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 51130
 Name of Operator: LOCIN OIL CORPORATION
 Address: 600 TRAVIS ST STE 6161
 City: HOUSTON State: TX Zip: 77002

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Trujillo, Aaron		aaron.trujillo@state.co.us	
Arnim, Rees	(713) 469-0275	rarnim@locin.energy	
Toews, Wesley J		wtoews@blm.gov	BLM West Slope

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119487	PIT	AC			-	Federal #4-10 119487	EI
211116	WELL	SI	06/01/2020	GW	045-06875	FEDERAL 4-10	EI

General Comment:

[ECMC Environmental Inspection.](#)

Location

Overall Good:

Signs/Marker:

Type			
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:
 Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Location Construction

Location ID: 323896 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: Stormwater ponding adjacent to the wellhead and on the northern section of the location.

Corrective Action: Comply with Rule 1002.f.(2)- Install or repair required stormwater and erosion control BMPs to properly divert stormwater runoff, and well as to stabilize the working pad surface, and to minimize tracking and off-site sediment transport. Ensure BMPs are installed in accordance with good engineering practices and maintained in a proper functioning condition; ongoing stormwater management required until Location receives a passing final reclamation inspection.

Date: 07/17/2024

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 119487 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 211116 Type: WELL API Number: 045-06875 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: 119487 Lat: 39.388111 Long: -108.982898

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Other Liner Condition: Inadequate

Comment: Pit Facility ID 119487 is filled with sediment.

Corrective Operator shall submit a Form 27 to close Pit Facility ID 119487. CA Date 6/16/2024

Date: 06/20/2024

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective

Date: _____

Netting:

Netting Type: Mesh Netting Condition: Gaps

Comment:

Corrective

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: NO

Comment:

Corrective

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	119487	400997587	
	119487	400997587	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700373	20240506 inspection	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6550462