

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION
Facility ID: 412030



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**

Section/Township/Range: 22 6S92W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION
Facility ID: 412030



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION
Facility ID: 412030



Photo # 7435 Failure to maintain chemical BMP - Chemical tank containment full of fluid/fluid overflowed containment & spilled on the ground



Photo # 7436 Failure to maintain chemical BMP - Chemical tank containment full of fluid/fluid overflowed containment & spilled on the ground

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION
Facility ID: 412030



Photo # 7437 Chemical tank containment evacuated of fluids by TEP employee



Photo # 7438 Chemical tank containment evacuated of fluids by TEP employee

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION
Facility ID: 412030



Photo # 7439 Chemical drums with no BMP's/during inspection TEP employee transferred drums to a metal containment