


COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	<div style="font-size: 2em; color: red; border: 1px solid red; border-radius: 50%; width: 40px; height: 40px; line-height: 40px; margin: 0 auto;">C</div> 1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
API No. 05- <u>123 - 9084</u>	LEASE NAME: <u>UPRR 43 G # 9</u>
LOCATION: <u>NE SW 29 IN 67W</u>	OPERATOR: <u>KPK</u>
DATE: <u>1/8/96</u>	INSPECTOR: <u>SHELTON</u>
Insp. Type: <u>1D</u>	Insp. Status: <u>TA</u>
PA: Y N	Pass/Fail: P <u>F</u>
	Viol.: <u>Y</u> N
	NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	<u>OK</u>	
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous	<u>TBG 1 RODS IN WELL / PUMP JACK DISMANTLED</u>	

CORRECTIVE ACTION REQUIRED: <u>COMPLY WITH RULE 324-6</u>	
Date Corrective Action Required By:	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.