

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/20/2024

Submitted Date:

05/22/2024

Document Number:

699700378

FIELD INSPECTION FORMLoc ID 334957 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210883	WELL	PR	05/23/1997	CBM	045-06641	EXXON GV 42-6	EI
210950	WELL	SI	10/01/2023	GW	045-06708	EXXON TW 11-6	EI
274468	WELL	PR	05/06/2005	GW	045-13354	PA 332-6	EI
274469	WELL	PR	10/29/2004	GW	045-13355	PA 432-6	EI
274470	WELL	PR	05/02/2005	GW	045-13356	PA 532-6	EI

General Comment:

ECMC Environmental Inspection.

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Erosion rills present south of the wellheads adjacent to the access road.

Corrective Action:

Comply with Rule 1002.f.(2)- Install or repair required stormwater and erosion control BMPs to properly divert stormwater runoff, and well as to stabilize the working pad surface, and to minimize tracking and off-site sediment transport.

Ensure BMPs are installed in accordance with good engineering practices and maintained in a proper functioning condition; ongoing stormwater management required until Location receives a passing final reclamation inspection.

Date: 05/27/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700379	20240520 Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6558502