

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY

FOR OFFICE USE ONLY			
ET	FE	UC	SE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. ☒ Oil Well ☐ Gas Well ☐ COALBEAD METHANE ☐ INJECTION WELL ☐ OTHER

2. NAME OF OPERATOR

Union Pacific Resources Company

3. ADDRESS OF OPERATOR

P.O. Box 7 MS 3006

CITY

Fort Worth,

STATE

TX

ZIP CODE

76101-0007

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements
See also space 12 below)
At Surface

At proposed prod. zone



12. COUNTY

Weld

5. FEDERAL INDIAN OR STATE LEASE NO.

6. PERMIT NO.

7. APINO

05-123-087700

8. WELL NAME

Zarlengo

9. WELL NUMBER

4-41-29

10. FIELD OR WILDCAT

Spindle

11. QTR., QTR., SEC., T.R., AND MERIDIAN

NENE Sec. 29 T1N R67 W

Check Appropriate Box to Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- ☐ PLUG AND ABANDON
- ☐ MULTIPLE COMPLETION
- ☐ COMMINGLE ZONES
- ☐ FRACTURE TREAT
- ☐ REPAIR WELL
- ☐ OTHER

13B. SUBSEQUENT REPORT OF:

- ☒ FINAL PLUG AND ABANDONMENT
(SUBMIT 3RD PARTY CEMENT VERIFICATION
AND JOB LOG)
- ☐ ABANDONED LOCATION (WELL NEVER DRILLED
SITE MUST BE RESTORED WITHIN 6 MONTHS)
- ☐ REPAIRED WELL
- ☐ OTHER

*Use Form 5 - Well completion or Recompletion Report and Log
for subsequent report of Multiple/Commingle Completions and
Recompletions

13C. NOTIFICATION OF:

- ☐ SHUT-IN TEMPORARILY ABANDONED
Date _____
(required every 6 months)
- ☐ PRODUCTION RESUMED
Date _____
- ☐ LOCATION CHANGE (SUBMIT NEW PLAT)
- ☐ WELL NAME CHANGE
- ☐ OTHER

14. DESCRIBE PROPOSED OR COMPLETED OPERATION ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent.

15. DATE OF WORK 6-14-96

Set CIBP at 4740'
Cap with 2 sacks
Cut and lay down casing from 3997'
Pump 80 Sack plug across surface shoe at 900'
Cut off well head
Dump 25 sack surface plug
Weld on plate and backfill

16. I hereby certify that the foregoing is true and correct

SIGNED

Cami Cho

TELEPHONE NO. (817) 877-6530

NAME (PRINT)

Cami Cho

TITLE

Regulatory Analyst

DATE

6-25-96

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE



50000142

DATE

7/5/96

CONDITIONS OF APPROVAL, IF ANY:

H & R WELL SERVICES, INC.
17509 ROAD 14
FORT MORGAN, COLORADO 80701


(303) 867-2730 • (303) 654-1600

TO

Union Pacific Resources Co.Brighton Colorado

DATE 6-14-96		JOB NO.	
PROJECT Spindle P&A			
LOCATION Zarlengo 4-41-29			
CONTRACTOR		OWNER	
WEATHER		TEMP.	° at AM ° at PM
PRESENT AT SITE			

THE FOLLOWING WAS NOTED:

Set CIBP at 4740'Cap with 2 sacksCut and lay down casing from 3997'Pump 80 Sack plug across surface shoe at 900'Cut off well headDump 25 sack surface plugWeld on plate and backfillHarlan Hodge P&A Supervisor


COPIES TO _____

FIELD REPORT

SIGNED _____

