

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

JUL 1 - 1996

FOR OFFICE USE ONLY			
ET	FE	UC	SE

SUBMIT ORIGINAL AND 1 COPY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. Oil Well Gas Well COALBEAD METHANE INJECTION WELL OTHER

2. NAME OF OPERATOR
Union Pacific Resources Company

3. ADDRESS OF OPERATOR
P.O. Box 7 MS 3006

CITY STATE ZIP CODE
Fort Worth, TX 76101-0007

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements
Sec also space 12 below)
At Surface

At proposed prod. zone



12. COUNTY
Weld

5. FEDERAL INDIAN OR STATE LEASE NO.

6. PERMIT NO.

7. API NO
05-123-87140

8. WELL NAME
Zarlengo

9. WELL NUMBER
3-32-29

10. FIELD OR WILDCAT
Spindle

11. QTR., QTR., SEC., T.R., AND MERIDIAN
SWNE S29 T1N R67W

Check Appropriate Box to Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- PLUG AND ABANDON
- MULTIPLE COMPLETION
- COMMINGLE ZONES
- FRACTURE TREAT
- REPAIR WELL
- OTHER _____

13B. SUBSEQUENT REPORT OF:

- FINAL PLUG AND ABANDONMENT (SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG)
 - ABANDONED LOCATION (WELL NEVER DRILLED SITE MUST BE RESTORED WITHIN 6 MONTH)
 - REPAIRED WELL
 - OTHER
- *Use Form 5 - Well completion or Recompletion Report and Log for subsequent report of Multiple/Commingled Completions and Recompletions*

13C. NOTIFICATION OF:

- SHUT-IN TEMPORARILY ABANDONED
Date _____
(required every 6 months)
- PRODUCTION RESUMED
Date _____
- LOCATION CHANGE (SUBMIT NEW PLAT)
- WELL NAME CHANGE
- OTHER _____

14. DESCRIBE PROPOSED OR COMPLETED OPERATION ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent.

15. DATE OF WORK 6-19-96

Set CIBP at 4790'
Cap with 2 sacks of cement
Cut casing at 3814' and lay down
Pump 80 sack plug across surface shoe at 900'
Dump 25 sack surface plug
Cut off well head
Weld on plate
Backfill hole

16. I hereby certify that the foregoing is true and correct

SIGNED Cami Cho TELEPHONE NO. (817) 877-6530

NAME (PRINT) Cami Cho TITLE Regulatory Analyst DATE 6-28-96

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE DATE 7/5/96

CONDITIONS OF APPROVAL IF ANY:



H & R WELL SERVICES, INC.
17509 ROAD 14
FORT MORGAN, COLORADO 80701

(303) 867-2730 • (303) 654-1600

TO Union Pacific Resources Co.

Brighton, Colorado

DATE 6-19-96		JOB NO.	
PROJECT Spindle P&A			
LOCATION Zarlengo 3-32-29			
CONTRACTOR		OWNER	
WEATHER		TEMP.	° at AM ° at PM
PRESENT AT SITE			

THE FOLLOWING WAS NOTED:

Set CIBP at 4790'

Cap with 2 sacks of cement

Cut casing at 3814' and lay down

Pump 80 sack plug across surface shoe at 900'


Dump 25 sack surface plug

Cut off well head

Weld on plate

Backfill hole

Harlan Hodge, P&A Supervisor



COPIES TO _____

FIELD REPORT

SIGNED _____

