



00060417

COLORADO OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		<div style="border: 1px solid red; border-radius: 50%; width: 40px; height: 40px; display: flex; align-items: center; justify-content: center; margin: 0 auto;">C</div> 1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 123 - 8803		LEASE NAME: DACONA # 2	
LOCATION: NW NW 2 IN 68W		OPERATOR: KPK	
DATE: 2/6/96		INSPECTOR: SHELTON	
Insp. Type: ID	Insp. Status: TA	PA: Y N	Pass/Fail: P <input checked="" type="radio"/> F Viol.: <input checked="" type="radio"/> Y N NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)	ON GROUND	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)		
<b>Fences</b> (Rule 604.C.(3), 1003.A)		
<b>Tank Battery Equipment</b> (Rule 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 604)		
<b>General Housekeeping</b> (Rule 603.G)		
<b>Spills (Oil/Water)</b> (Rule 908)		
<b>Bradenhead</b> (Rule 207)		
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)		
<b>Miscellaneous</b>	PUMP JACK REMOVED / TBG LOOKING UP	

## CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site