



00205522

RECEIVED

OCT 24 1990

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY

COLO. OIL & GAS CONS. COMM

FOR OFFICE USE ONLY			
ET	FE	UC	SE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> COALBED METHANE <input type="checkbox"/> INJECTION WELL <input checked="" type="checkbox"/> OTHER		5. FEDERAL/INDIAN OR STATE LEASE NO.
2. NAME OF OPERATOR JENEX Petroleum Corporation		6. PERMIT NO.
3. ADDRESS OF OPERATOR 1675 Larimer Street, Suite 810 CITY STATE ZIP CODE Denver, Colorado 80202		7. API NO. 05-123-12317
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface SW/4NW/4 At proposed prod. zone SAME		8. WELL NAME Owl Creek
12. COUNTY Weld		9. WELL NUMBER 32
		10. FIELD OR WILDCAT Tom Cat
		11. QTR. QTR. SEC., T.R. AND MERIDIAN 1-T7N-R64W

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- ☒ PLUG AND ABANDON
☐ MULTIPLE COMPLETION
☐ COMMINGLE ZONES
☐ FRACTURE TREAT
☐ REPAIR WELL
☐ OTHER _____

13B. SUBSEQUENT REPORT OF:

- ☐ FINAL PLUG AND ABANDONMENT
(SUBMIT 3RD PARTY CEMENT VERIFICATION
AND JOB LOG)
☐ ABANDONED LOCATION (WELL NEVER DRILLED -
SITE MUST BE RESTORED WITHIN 6 MONTHS)
☐ REPAIRED WELL
☐ OTHER

*Use Form 5 - Well Completion or Recompletion Report and Log
for subsequent report of Multiple/Commingle Completions
and Recompletions

13C. NOTIFICATION OF:

- ☐ SHUT-IN/TEMPORARILY ABANDONED
(DATE _____)
(REQUIRED EVERY 6 MONTHS)
☐ PRODUCTION RESUMED
(DATE _____)
☐ LOCATION CHANGE (SUBMIT NEW PLAT)
☐ WELL NAME CHANGE
☐ OTHER _____

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent

15. DATE OF WORK October 24, 1990

Set bridge plug above perforations.

Set 2 sacks of cement on top of bridge plug.

Perforate and cut 4 1/2" production casing at free point.

Pull and lay down 4 1/2" production casing.

Set 200' of cement half-in and half-out of surface pipe (726').

Set 5 sacks of cement at top of surface pipe.

Cut off surface pipe off 4' below ground and weld on steel cap.

Remove deadmen, back fill pits, cleanup and level location.

16. I hereby certify that the foregoing is true and correct

SIGNED

TELEPHONE NO. 292-4051

NAME (PRINT)

Alvin R. (Al) Arlian

TITLE

Agent

DATE

10-24-90

(This space for Federal or State office use)

APPROVED

TITLE

Sr. Engr.

DATE

11/14/90

CONDITIONS OF APPROVAL, IF ANY: