

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2024

Submitted Date:

05/24/2024

Document Number:

710500288**FIELD INSPECTION FORM**Loc ID 333545 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10758Name of Operator: OGRIS OPERATING LLCAddress: PO BOX 53467City: MIDLAND State: TX Zip: 79710**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Zeches, Giena	719-220-4041	gzeches@ogrisop.com	
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections

General Comment:[This is an Environmental Inspection for the Apache Canyon 06-10, Remediation location located in Las Animas County, Co. Remediation # 22862](#)

Location				
Lease Road:				
Type				
comment:	Access road remains through well pad.			
Corrective ActionL			Date:	
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:	No well placard identified on the location for the Apache Canyon 06-10			
Corrective Action:	Install sign to comply with Rule 605.a.			Date: 06/25/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Environmental		
Spill/Remediation:		
Comment:	Remediation Project # 22862 is ongoing, Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area	
Corrective Action:		Date: _____
Emission Control Burner (ECB): _____		
Comment:		
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<div>Comment: Operator shall maintain BMPs and minimize erosion in accordance with Rule 1003 until the site is ready for final reclamation</div> <div>Corrective Action: <div></div> Date: <div></div></div> <div>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</div>						

ECMC Comments

Comment	User	Date
Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area	sanchezcc	05/24/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500289	Inspection 710500288 Location Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6571400