

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2024

Submitted Date:

05/29/2024

Document Number:

699108642

FIELD INSPECTION FORMLoc ID 453038 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453047	WELL	PR	10/01/2021	OW	123-45886	Jagged 9N	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around the well needs to be removed. See attached photo.		
Corrective Action:	. "Properly dispose of oily waste in accordance with 905.e."		Date: 07/12/2024

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 453047 Type: WELL API Number: 123-45886 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 04/15/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 13 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
ECMC Inspection Report Summary On Tuesday, May 28, 2024, at approximately 8:40 AM, Inspector Adam Burns conducted an on-site inspection at the following location: Location: Jagged 9N Operator: Chevron/PDC API: 05-123-45886 County: Weld During the inspection, a shut in well was observed. The following possible compliance issues were identified: Stained Soil: Stained soil around the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." Corrective Action deadline: 7/12/2024. A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.	burnsa	05/29/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403807766	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567682
699108643	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567675