

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403815966

Date Received:

06/06/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Abdul Elnajdi

abdul.elnajdi@state.co.us

Kyle Waggoner

kyle.waggoner@state.co.us

Dolezal, Pat

pat.dolezal@ownresources.com

Kilian Collins

kilian.collins@state.co.us

Krystal Heibel

krystal.heibel@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100284

Inspection Date: 04/24/2024

FIR Submit Date: 05/07/2024

FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC

Company Number: 10699

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 337808

Location Name: KNODEL-64S42W Number: 16NWNW County: _____

Qtrqtr: NWN Sec: 16 Twp: 4S Range: 42W Meridian: 6
W

Latitude: 39.715230 Longitude: -102.081520

FACILITY - API Number: 05-125- -00 Facility ID: 337808

Facility Name: KNODEL-64S42W Number: 16NWNW

Qtrqtr: NWN Sec: 16 Twp: 4S Range: 42W Meridian: 6
W

Latitude: 39.715230 Longitude: -102.081520

CORRECTIVE ACTIONS:

1 CA# 194944

Corrective Action:

Date: 07/07/2024

Operator shall remediate the historic release by delineating horizontal and vertical extent of impacted area using the Table 915-1 Protection of Groundwater Soil Screening Level Concentrations and remediate impacts to Table 915-1 standards. Documentation must include a figure showing spill area with sample locations plus laboratory results. This information shall be submitted within the next Form 27 submittal.

Response: CA COMPLETED

Date of Completion: 05/10/2024

Operator Comment: Soil samples have been taken for rem#34576

ECMC Decision:

ECMC Representative:

2 CA# 194945

Corrective Action: Comply with Rule 606.

Date: 05/14/2024

Response: CA COMPLETED

Date of Completion: 05/10/2024

Operator Comment: No growing tumbleweeds were found on location during area foreman inspection. Tumbleweeds that had encamped inside fencing due to wind were removed.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Pat Dolezal

Signed:

Title: Regulatory Specialist

Date: 6/6/2024 11:47:17 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files