

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403786649

Date Received:

06/11/2024

## FIR RESOLUTION FORM

**Overall Status:**

**CA Summary:**

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 708903254

Inspection Date: 03/11/2024

FIR Submit Date: 03/11/2024

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**LOCATION - Location ID: 335438**

Location Name: SILT VALLEY-66S92W Number: 22SESE County: \_\_\_\_\_

Qtrqtr: SESE Sec: 22 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.507761 Longitude: -107.647183

**FACILITY - API Number: 05-045- -00 Facility ID: 335438**

Facility Name: SILT VALLEY-66S92W Number: 22SESE

Qtrqtr: SESE Sec: 22 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.507761 Longitude: -107.647183

**CORRECTIVE ACTIONS:**

1 CA# 192940

Corrective Action: The storage or placement of equipment and supplies not necessary for use on location is prohibited.

Date: 04/10/2024

Response: CA COMPLETED

Date of Completion: 05/02/2024

Operator Comment: ECD has been reconnected and is currently in use. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

Date: 03/14/2024

Date of Completion: 05/02/2024

Fluid in chemical containment has been removed, rip rap has been repaired, and the rill has been repaired. Location has been further stabilized to prevent off location runoff. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

\_\_\_\_\_

Comment:	CA #192940: ECD has been reconnected and is currently in use. Corrective Action complete. CA #192941: Fluid in chemical containment has been removed, rip rap has been repaired, and the rill has been repaired. Location has been further stabilized to prevent off location runoff. Corrective Action complete.
----------	--

Title: TEP Representative Date: 6/11/2024 9:42:22 AM

--	--

Page 2 of 2