

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403787085

Date Received:
06/12/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:
 2 of 2 CAs from the FIR responded to on this Form
 2 CA Completed
 0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: <u>96850</u>	Contact Name and Telephone:
Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u>	Name: _____
Address: <u>1058 COUNTY ROAD 215</u>	Phone: () _____ Fax: () _____
City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>	Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708301795
 Inspection Date: 03/05/2024 FIR Submit Date: 03/07/2024 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335111

Location Name: WILLIAMS-66S96W Number: 34NWSW County: _____
 Qtrqtr: NWS Sec: 34 Twp: 6S Range: 96W Meridian: 6
W
 Latitude: 39.479743 Longitude: -108.100019

FACILITY - API Number: 05-045-00 Facility ID: 335111

Facility Name: WILLIAMS-66S96W Number: 34NWSW
 Qtrqtr: NWS Sec: 34 Twp: 6S Range: 96W Meridian: 6
W
 Latitude: 39.479743 Longitude: -108.100019

CORRECTIVE ACTIONS:

1 CA# 192813	
Corrective Action: <u>Install sign to comply with Rule 605.d.</u>	Date: <u>04/06/2024</u>
Response: <u>CA COMPLETED</u>	Date of Completion: <u>04/10/2024</u>
Operator Comment: <u>New wellhead signs have been installed. Corrective Action complete.</u>	
ECMC Decision: _____	

ECMC
Representative:

2 CA# 192814

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/22/2024

Response: CA COMPLETED

Date of Completion: 05/20/2024

Operator
Comment:

Location and access road have been bladed/graded to remove rutting. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #192813: New wellhead signs have been installed. Corrective Action complete.
CA #192813: Location and access road have been bladed/graded to remove rutting. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 6/12/2024 7:44:00 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files