

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2024

Submitted Date:

06/14/2024

Document Number:

699505939

FIELD INSPECTION FORMLoc ID 318651 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241810	WELL	PR	08/01/2023	OW	123-09599	UPRR 42 PAN AM AN 2	PR

General Comment:[There have been no changes to equipment on location since previous inspection.](#)

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:			Date:		
Flaring:					
Type					
Comment:					
Corrective Action:			Date:		

Inspected Facilities									
Facility ID:	241810	Type:	WELL	API Number:	123-09599	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	08/02/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
ECMC Comments									
Comment				User			Date		
This inspection does not nullify any orders or corrective actions from the ECMC At time of inspection weather conditions were warm, overcast, calm.				medinaj		06/14/2024			
Attached Documents									
You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:									
Document Num	Description		URL						
699505940	inspection pictures		https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6588740						