

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403796500

Date Received:  
06/18/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302139  
Inspection Date: 05/07/2024 FIR Submit Date: 05/08/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 422301

Location Name: Speakman Number: A Pad County: \_\_\_\_\_  
Qtrqtr: NESW Sec: 24 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.421017 Longitude: -108.060560

FACILITY - API Number: 05-045- -00 Facility ID: 422301

Facility Name: Speakman Number: A Pad  
Qtrqtr: NESW Sec: 24 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.421017 Longitude: -108.060560

CORRECTIVE ACTIONS:

**1** CA# 194977

Corrective Action: Remove debris to comply with Rule 606. Date: 05/28/2024

Response: CA COMPLETED Date of Completion: 05/20/2024

Operator Comment: Debris on east side of location has been removed. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 194978

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 02/10/2024

Response: CA COMPLETED

Date of Completion: 06/06/2024

Operator Comment: Gravel has been hauled in and the location and access road have been bladed/graded to increase stabilization. VTC has been maintained. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA #194977: Debris on east side of location has been removed. Corrective Action complete.  
CA #194978: Gravel has been hauled in and the location and access road have been bladed/graded to increase stabilization. VTC has been maintained. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 6/18/2024 5:57:31 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files