

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403828204

Date Received:

06/18/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Mollie O'Hare

Phone

970-563-4000

Email

mollieo@maralexinc.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000740

Inspection Date: 05/02/2024

FIR Submit Date: 05/06/2024

FIR Status: _____

Inspected Operator Information:

Company Name: MARALEX RESOURCES INC

Company Number: 53255

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

LOCATION - Location ID: 333661

Location Name: KEEGAN PRTRICK-N33N7W Number: 11NWNW County: _____

Qtrqtr: NWN Sec: 11 Twp: 33N Range: 7W Meridian: N
W

Latitude: 37.122820 Longitude: -107.582665

FACILITY - API Number: 05-067- -00 Facility ID: 333661

Facility Name: KEEGAN PRTRICK-N33N7W Number: 11NWNW

Qtrqtr: NWN Sec: 11 Twp: 33N Range: 7W Meridian: N
W

Latitude: 37.122820 Longitude: -107.582665

CORRECTIVE ACTIONS:

2 CA# 194932

Corrective Action: comply with rule 608 Install or repair wildlife protection equipment.

Date: 05/11/2024

Response: CA COMPLETED

Date of Completion: 06/17/2024

Operator
Comment:

We tightened the netting and at the request of Cory McDonough, placed a wooden stick in the pan for critters in case they get trapped.
Please be aware that this location has a serious snake problem. A seven-foot bull snake lives under this pan. A pumper pulled a 12-foot snake out of the meter house recently, and a third snake, about six feet long, has also been hanging out on this location. It is likely that small mammals are the draw for these reptiles.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: We tightened the netting and at the request of Cory McDonough, placed a wooden stick in the pan for critters in case they get trapped.
Please be aware that this location has a serious snake problem. A seven-foot bull snake lives under this pan. A pumper pulled a 12-foot snake out of the meter house recently, and a third snake, about six feet long, has also been hanging out on this location. It is likely that small mammals are the draw for these reptiles.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mollie O'Hare

Signed: _____

Title: E.A.

Date: 6/18/2024 11:58:13 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403828248	PHOTOS - DAY TANK WILD LIFE ISSUE RESOLVED
-----------	--

Total Attach: 1 Files