

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403808735

Date Received:
06/19/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708301974

Inspection Date: 04/04/2024

FIR Submit Date: 04/06/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334794

Location Name: FEDERAL Number: GM 41-8 County: _____

Qtrqtr: LOT 1 Sec: 8 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.458398 Longitude: -108.123450

FACILITY - API Number: 05-045-00 Facility ID: 334794

Facility Name: FEDERAL Number: GM 41-8

Qtrqtr: LOT 1 Sec: 8 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.458398 Longitude: -108.123450

CORRECTIVE ACTIONS:

1 CA# 194059

Corrective Action: Install sign to comply with Rule 605.e.

Date: 05/06/2024

Response: CA COMPLETED

Date of Completion: 05/20/2024

Operator Comment: New battery sign has been installed. Corrective Action complete.

ECMC Decision: _____

ECMC Representative:		
2	CA# 194060	
Corrective Action:	1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.	Date: 04/21/2024
Response:	CA COMPLETED	Date of Completion: 05/20/2024
Operator Comment:	Location and access road have been bladed/graded to remove rutting and increase stabilization. Corrective Action complete.	
ECMC Decision:		
ECMC Representative:		

OPERATOR COMMENT AND SUBMITTAL	
Comment:	CA# 194059: New battery sign has been installed. Corrective Action complete. CA# 194060: Location and access road have been bladed/graded to remove rutting and increase stabilization. Corrective Action complete.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Jordan Veith	Signed: _____
Title: TEP Representative	Date: 6/19/2024 8:07:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description

Total Attach: 0 Files