

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403794150

Date Received:

06/18/2024

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708901964

Inspection Date: 10/11/2023

FIR Submit Date: 10/15/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 324007

Location Name: GOAD-66S94W Number: 34NESW County: \_\_\_\_\_

Qtrqtr: NESW Sec: 34 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.478620 Longitude: -107.877939

### FACILITY - API Number: 05-045- -00 Facility ID: 324007

Facility Name: GOAD-66S94W Number: 34NESW

Qtrqtr: NESW Sec: 34 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.478620 Longitude: -107.877939

### CORRECTIVE ACTIONS:

1 ☒ CA# 185148

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 10/30/2023

Response: CA COMPLETED

Date of Completion: 11/08/2023

Operator  
Comment:

Culvert on lease road and Rip Rap have been repaired. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Culvert on lease road and Rip Rap have been repaired. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 6/18/2024 5:25:27 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403794150	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files