

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/16/2024

Submitted Date:

06/20/2024

Document Number:

694500675

**FIELD INSPECTION FORM**

Loc ID 312953 Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 6720  
Name of Operator: ROBERT L BAYLESS PRODUCER LLC  
Address: 621 17TH ST STE 2300  
City: DENVER State: CO Zip: 80293

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		htrujillo@rlbayless.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223008	WELL	SI	11/01/2023	OW	081-06370	DEER CREEK STATE 1 (16-4-91)	EI

**General Comment:**

Environmental staff, Kris Neidel inspected the well pad. The well was not pumping at the time of inspection. The following was observed on the pad; pumping unit with gas motor, a propane tank, 1 above ground tank in steel containment. Any corrective action(s) from previous inspections that have not been addressed are still applicable See attached See attached Photos.

**Inspected Facilities**

Facility ID: 223008 Type: WELL API Number: 081-06370 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500676	photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595300">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595300</a>